

02910.000014.



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
: Examiner: S.S.Y. Lee
SHINYA YAMAMOTO ET AL.)
: Group Art Unit: 2852
Appln. No.: 10/079,894)
:
Filed: February 22, 2002)
:
For: DEVELOPER REGULATING MEMBER)
AND DEVELOPING APPARATUS :
INCLUDING THE SAME)
:
U.S. Patent No.: US 6,795,672 B2)
:
Issued: September 21, 2004) January 13, 2005

Certificate
JAN 25 2005
of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION
UNDER RULE 322

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form, in duplicate, is enclosed.

JAN 25 2005

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Peter Saxon
Attorney for Patentees
Registration No. 24,947

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_Main 464602v1

JAN 25 2005

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,795,672 B2

DATED : September 21, 2004

INVENTOR(S) : SHINYA YAMAMOTO ET AL

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Lines 35-36, "Thickness t (μm)	should read -- Thickness t (μm)
1000	1000
500	500
200	300
300	200
100	100
20	20
5"	5--.

COLUMN 13:

Line 34, "member:" should read --member;--.

COLUMN 14:

Line 21, "contains" should be deleted; and
Line 22, "300 λm," should read --300 μm,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,795,672 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,795,672 B2

DATED : September 21, 2004

INVENTOR(S) : SHINYA YAMAMOTO ET AL

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Lines 35-36, "Thickness t (μ m)	should read -- Thickness t (μ m)
1000	1000
500	500
200	300
300	200
100	100
20	20
5"	5--.

COLUMN 13:

Line 34, "member:" should read --member;--.

COLUMN 14:

Line 21, "contains" should be deleted; and

Line 22, "300 λ m," should read --300 μ m,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,795,672 B2

No. of add'l. copies
@ 30¢ per page

